



Electronic Service Manuals

This electronic document is provided as a service to our customers. We do not create the contents of the information contained in this document. Should you have detailed questions pertaining to the information contained in this document, you may contact Michco, or the manufacturer which provided the original information in this electronic deliverable. Michco's only part in this electronic deliverable was the electronic assembly process.

You may contact Michco through the following methods:
Phone (517) 484-9312 or (800) 331-3339 MI, OH, IN only
2011 N. High St. -- Lansing, Michigan -- 48906
Fax: (517) 484-9836
Email: CustServ@Michco.com
Web site: www.Michco.Com
Parts Web site: www.FloorMachineParts.Com

Order Parts on Line at:
www.FloorMachineParts.Com

Directly to Parts & Service:
By Email: **Shop@Michco.com**
By Fax: (517) 702-2041
By Voice: Use numbers above.

Serving the Cleaning Industry Since 1922

Notice: All copyrighted material remains property of original owners, all trademarks are property of respective owners. Manuals are subject to Manufacturer's reproduction limitations. Originals or reproductions were provided by manufacturers through a request. We make no warranty as to the correctness of information provided in this document and you assume all risk.

AC MOTOR PARTS LIST

for

Single Speed Polishers

ITEM	DESCRIPTION	1 HP MOTOR & GEAR ASM. 115V 60C		1.5 HP MOTOR & GEAR ASM. 115V 60C		
		505253-1HP Motor 115V/60C	505297-1HP Motor #36J377Y799	505254-1.5HP Motor	505273-1.5HP Motor #36J377T115	505249 -1.5HP Motor AD15017 (Chrome)
		503535 Gear Asm. 10:1 - 3 Idler	503522 Gear Asm. 10:1 - 2 Idler	503535 Gear Asm. 10:1 - 3 Idler	503523 Gear Asm. 10:1 - 3 Idler	503523 Gear Asm. 10:1 - 3 Idler
						505251 - Motor & Gear Asm.
A	Ring Gear Housing		504209		504209	504209
B	Bearing, Ring Gear Hsing	902007	902007	902007	902007	902007
C	Planet Gear Hsing		504216		504208	504208
D	Bearing, Pinion Lower	902005	902005	902005	902005	902005
E	Screw-Ring Gear Hs.					
F	Screw, Planet Gear Hsing					
G	Motor Cord		908090		908090	
H	Run Capacitor	911279 - 40MFD/400V	911235 - 40MFD/370V	911286 - 60MFD/400V	911236 - 60MFD/240V	911305 - 60MFD/250V
I	Cover,Run Capacitor	502308	502375	502308	502375	
J	Cover, Start Capacitor	502308	502375	502308	502375	
K	Start Capacitor	911278 - 470MFD/125V	911239-400/480MFD-115V	911278 - 470MFD/125V	911239-400/480MFD-115V	911304 - 450MFD/165V or 300V
L	Bolt		960035		960035	
M	End Bell		502931		502931	
N	Stator Asm,115V-60C		503124		503130	
O	Bearing, Motor Top	902038	902003	902038	902003	902003
P	Stationary Switch	911277	911251	911277	911251	911306
Q	Rotary Switch		911219		911289	911307
R	Rotor Assembly	500436	500428	500437	500434	
S	End Bell-Motor Lower		502927		502927	502927
T	Cover, Ring Gear		502317		502317	502317
U	Bearing, Upper Gear Hsing	902015	902015	902015	902015	902015
V	Bearing, Pinion Upper	902005	902005	902005	902005	902005
X	Coupling Flexible	502460	502460	502460	502460	502460
Y	Spacer		508211		508211	508211
Z	Pinion		503510		503510	503510
AA	Shaft-Planet Gear		507701 (Qty.2)		507701 (Qty.3)	507701 (Qty.3)
BB	Bearing-Planet Shaft		902016 (Qty.4)		902016 (Qty.6)	902016 (Qty.6)
CC	Gear-Planet		503511 (Qty.2)		503511 (Qty.3)	503511 (Qty.3)

AC MOTOR ILLUSTRATION

